

2003 Marquis Addendum



The information printed here reflects product design, fabrication, and component parts at the date of printing. Due to product improvements, changes during the model year and/or transcription errors that may occur, information represented within this document may not be accurate at the time of purchase. Please confirm any information with the dealership.

The manufacturer reserves the right, at any time, to make changes in product design or material or component specifications as its sole option, without notice. This includes the substitution of components of a different brand or trade name, which will result in comparable performance. All information printed in this document is subject to change after the date of printing. Some features shown or mentioned in this document are optional and may only be available in selected floorplans.

©Copyright Monaco Coach Corporation. All rights reserved. All trademarks or registered trademarks are property of their respective holders. Brand name products of other companies mentioned in this addendum are not endorsed by Monaco Coach Corporation.

Information on page 51 “Emergency Roadside Procedures - Jump Starting” needs to be updated to reflect the following changes:

EMERGENCY ROADSIDE PROCEDURES

In the event of a roadside emergency, *contact the nearest Caterpillar Center at 1-800-447-4986 for Caterpillar Customer Assistance Center.*

The information for the Liquid Soap Dispenser was omitted from section six of the manual. The following information should be placed on page 211:

LIQUID SOAP DISPENSER

The liquid soap/lotion dispenser can be used with any type of liquid soap or lotion. The liner of the bottle will not corrode or discolor the contents of the dispenser. To clean, use a soft cloth and blot dry. Do not use harsh abrasive cleanser or polishes, this can damage the finish on the dispenser.



Liquid Soap Dispenser



Funnel for re-filling the dispenser.

Additionally as a result of a transcription error on page 301, the note should read as follows:

AUXILIARY BRAKE




NOTE: When the Auxiliary Braking device is used, the display will change to a default reading of “4”. This setting is pre-selected at the factory and can only be altered by an authorized Allison Service center. The transmission is not actually in “fourth” gear. This is only a reference point so the transmission will optimize engine braking efficiency.

Information on page 388 needs to be updated to reflect the following omissions:

LUBRICATION CHART

27: Air filter Minder	Inspect	Daily	--
28: Axle Breather	Inspect	250,000 or 3 years	--

Drawing number 070174F on page 389 is for early year units.
 Replace the drawing with 070174J for later year models.





91320 Coburg Industrial Way
Coburg, OR 97408

www.beavermotorcoaches.com

Warranty/Technical Support
Toll Free 1-800-344-6332