

***Air Conditioner  
Charge***

---

***2005***

---

***Monterey***

The information printed here reflects product design, fabrication, and component parts at the date of printing. The manufacturer reserves the right, at any time, to make changes in product design or material or component specifications as its sole option, without notice. This includes the substitution of components of a different brand or trade name, which will result in comparable performance. All information printed in this document is subject to change after the date of printing. Due to product improvements, changes during the model year and/or transcription errors that may occur, information represented within the owner's manual and/or this document may not be accurate at the time of your purchase. Please confirm any information with your dealer.

The following information supersedes the information published in the 2005 Monterey Owner's Manual in Section 9 page 373. Please utilize the information provided henceforth.

**©Monaco Coach Corporation. Beaver Motor Coach. All rights reserved. All other trademarks or registered trademarks are property of their respective holders. Brand name products of other companies mentioned in this addendum are not endorsed by Monaco Coach Corporation.**

The refrigerant charge information for the 2005 Monterey on page 373 is incorrect. The following information supersedes the printed in the manual.

**NOTE:**

**All systems are charged at the factory with 4.0 lbs of R134a. A fluorescent dye has been added for leak detection.**

*“Change is italicized”*



**Safari Motor Coach**

P.O. Box 5639

Bend, OR 97708

[www.beavermotorcoach.com](http://www.beavermotorcoach.com)

**Warranty/Technical Support**

Toll Free 800-344-6332